

FITNESS CERTIFICATE OF SCHOOL BUILDING - ANNEXURE B

1	Name of school	PALLOTTI HILLS PUBLIC SCHOOL
2	Name of Officer preparing report	Safeeda. N. P, Assistant Engineer, LSGD Section, Mukkam Municipality
3	Location	Mukkam
4	Period for which the certificate is issued	2026-27
5	Types of building(dimensions are in m)	RCC Framed structure
	Ground floor	4 class rooms - 7.00 x 6.30 m x 3.70M staff room - 1 x 10.00 x 3.00 x 3.70M Computer room- 1 x 9.30x 5.80x 3.70M
	First Floor	4 class rooms - 7.00 x 6.30 m x 3.70M staff room - 1 x 10.00 x 3.00 x 3.70M Principal room- 1 x 6.50x 6.00x 3.70M Office - 1 x 6.50x 6.00x 3.70M Library - 1 x 6.10x 9.50x 3.70M Reading room - 1 x 12.80x 5.80x 3.70M
	Second Floor	4 class rooms - 7.00 x 6.30 m x 3.70M staff room - 1 x 10.00 x 3.00 x 3.70M Laboratory - 1 x 12.80x5.80x 3.70M Office - 1 x 6.50x 6.00x 3.70M 1 x9.50x 6.10x 3.70M 1 x 13.20x6.00x 3.70M
6	Nature of defect if any	Nil
(a)	Foundation and basement	Nil
(b)	Super structure	Nil
(c)	Doors and windows	Nil
(d)	Woodwork wrought and pitup	Nil
(e)	Roof	Nil
(f)	Flooring	Nil
(g)	Miscellaneous (Ctracks if any)	Nil
7	Any major defects notices which will render the building unsafe if any manner	No



8 Whether maintenance work have been done properly

Yes

9 Whether the structure is sound or not for conducting classes

yes, The structure is sound for conducting classes under normal weather conditions for the period of 2026-27

Note: 1 The stability of the structure should be examined also with reference to location altitude intensity of wind exposure to flood etc.,

2 Any additional observation deemed necessary for the certificate, may be furnished separately with the certificate

Certified that the school was inspected by me on 15/05/2026 and above noted classes are found to be fit to conduct classes for the period for the reasons stated above with the following conditions.

1. This certificate is applicable only to safety related to civil construction. Separate certificates for fire safety and safety of electrical installations, electrical lines/conduits shall be obtained from the concerned departments.

2. Maintenance of the school premises should be done periodically. The inspecting officer is not liable for any unfortunate accidents in the school premises due to lack of security or periodic maintenance.

3. This certificate is only for the structural safety of the classrooms mentioned in this certificate. It does not cover safety in laboratories, kitchens, etc.

4. For any new construction in the school compound, it should be intimated and a permit should be obtained from LSGI. Safety measures such as barricades must be ensured.

5. Internal wiring of the school should be verified by a registered /Approved Electrician before conducting classes

6. This fitness certificate is issued based on circular No: GEDN-M1/188/2025-G.EDN by General Education(M)Department Thiruvananthapuram dated 13/05/2026 ,Letter No GEDN-M1/188/2025-G.EDN dated 25/05/2026 and Circular No -LSGD/2037/2026-EW3 dated 26/05/2026 by Chief Engineer, Principal Directorate, LSGD.

7. ANNEXURE B IS ISSUED IN COMPLIANCE WITH ANNEXURE A (CHECK LIST)

8. Additional construction in the school premises(Third floor) should be regularised.

Place Mukkam

Signature

Date 01/08/2026

Designation

SAFEEDA N.P

Pen 941438

ASSISTANT ENGINEER

Mukkam Municipality

Pin - 673602

